

Notification Date: April 20, 2020

Effective Date: April 20, 2020

PRODUCT CHANGE NOTIFICATION

DIN Rail Bracket Replacement

Product Identification

List of all Affected Products:

- **v2 routers** (Bivias, CR10 v2, ER75i v2, LR77 v2, LR77 v2L, RR75i v2, SPECTRE, UR5i v2, UR5i v2L, XR5i v2 and XR5i v2E) **in metal case**
- **v3 routers** (SmartFlex, SmartMotion) **in metal case**

Issue Description

Detailed Description of the Issue: Due to the supply shortage of the BB-SBD40 DIN rail mounting bracket, caused by international transport paralyzed with the worldwide pandemic, the bracket will be temporarily replaced with BB-SBD45 bracket.

Anticipated Impact

Detailed Description of the Impact: The replacement, BB-SBD45 DIN rail mounting bracket, is 5 mm higher than the original one. For this reason, the bracket exceeds the rear panel of the v2 router by 2.5 mm, see Figure 1.



Figure 1: BB-SBD45 DIN Bracket on v2 Router

The BB-SBD45 DIN rail mounting bracket, mounted on a v3 router, is displayed on Figure 2.




Figure 2: BB-SBD45 DIN Bracket on SmartFlex Router