

**Notification Date:** November 25, 2020  
**Effective Date:** December 1, 2020

## PRODUCT CHANGE NOTIFICATION

# DIN Rail Bracket Replacement

### Product Identification

#### List of all Affected Products:

- **ICR-3200 routers:** *ICR-3201(W)*, *ICR-3231(W)*, *ICR-3232(W)*, *ICR-3241(W)* and *ICR-3211B*.
- **Accessories:** DIN rail mounting bracket kit sold as accessories under P/N *BB-DIN-ICR32*.

### Issue Description

**Detailed Description of the Issue:** The *BB-DIN-ICR32* DIN rail mounting bracket will be replaced with another type due to the supply shortage. This new bracket was successfully tested and comply with all the quality requirements and has no functional impact.

### Anticipated Impact

**Detailed Description of the Impact:** The new DIN rail bracket is 5 mm lower than the original one, see Figure 1.



Figure 1: Comparison of the Original and the New One Bracket