

**Notification Date:** September 6, 2022

## PRODUCT CHANGE NOTIFICATION

### SIM Slot Replacement

#### Product Identification

**List of all Affected Products:**

- **SmartStart** (BB-SL305)
- **SmartFlex** (BB-SR303, BB-SR304, BB-SR305, BB-SR307, BB-SR308, BB-SR309, BB-SR310)
- **SmartMotion** (BB-ST352, BB-ST355)
- See the revision number printed on the packaging box or the product label to identify affected routers. Affected routers have revision 2.0; see Figures 1 and 2.



Figure 1: Revision on the Packaging Label



Figure 2: Revision on the Product Label

## Change Description

### Detailed Description of the Change:

- We have replaced the obsolete [1050340001](#) SIM slot embedded on the module board with a new Molex [475530001](#) SIM slot.
- The reason for this is the end of production of the original slot.

## Anticipated Impact

### Detailed Description of the Impact:

- Since the effective date, the new SIM slot type will be assembled to the module board of affected routers.
- The basic mechanical parameters of the slot remain unchanged.
- However, when handling SIM cards, the new slot may exhibit different subjective characteristics due to the different mechanical designs of the slot.

## Qualification Data

The new version of the product fulfills all internal quality requirements according to our Quality Management process and philosophy.