# ICR-1601 Firmware

## RELEASE NOTES

FW code: e81

# Abstract

This document contains the changelog of all new features, fixes and other changes implemented in firmware. For detailed information about firmware of e81 code, see the Configuration Manual for your router.

# Firmware Details

- **Short firmware version code**: e81

- **Full firmware version code**: IA2_e81.0CN0_03131800

- **Release date**: October 4, 2018

- **Hardware compatibility**: This firmware is applicable only to routers of ICR-1601 family made by Advantech.

# Changelog

**Legend:** Affected products are marked as shown below for every changelog item:

| Affected product | Not affected product |

## Support for Auto Update

| ICR-1601G | ICR-1601W |

Added support for Firmware or Config Auto Update function. Both can be updated by files stored at an HTTP(S)/FTP(S) server.

To set this feature go to *Administration -> System Operation -> Backup & Restore* tab and open *Auto Upgrade* form below.