ICR-1601 Firmware

RELEASE NOTES

FW code: eA9

Abstract

This document contains the changelog of all new features, fixes and other changes implemented in firmware. For detailed information about firmware of eA9 code, see the Configuration Manual for your router.

Firmware Details

- **Short firmware version code**: eA9

- **Full firmware version code**: IA2_eA9.0CN0

- **Release date**: August 8, 2020

- **Hardware compatibility**: This firmware is applicable only to routers of ICR-1601 family made by Advantech.

Changelog

Legend: Affected products are marked as shown below for every changelog item:

Affected product   Not affected product

Fixed VLAN Issue

ICR-1601G   ICR-1601W

Fixed Inter VLAN Group Routing of VLAN issue.