

# Firmware Compatibility Chart

Notification Date: October 8, 2024

Page: 1 of 3



| Product Platform | Product Family | Product Name    | FW Version   | FW File Name                                |
|------------------|----------------|-----------------|--|---|
| lite             | ICR-1601       | ICR-1601G       | OCN0XJG.IA2_eA9.<br>OCNO_07021000  | ICR_1601G_OCN0XJG.IA2_eA9.OCNO_07021000.bin |
|                  |                | ICR-1601W       | OCN0XJW.IA2_eA9.<br>OCNO_07021000  | ICR_1601W_OCN0XJW.IA2_eA9.OCNO_07021000.bin |
| v2               | Spectre v2     | SPECTRE RT      | 6.3.12   | SPECTRE-RT.bin                              |
|                  | Conel v2       | ER75i v2        | 6.3.12   | ER75i-v2.bin                                |
|                  |                | UR5i v2         | 6.3.12   | UR5i-v2.bin                                 |
|                  |                | XR5i v2         | 6.3.12   | XR5i-v2.bin                                 |
|                  |                | LR77 v2         | 6.3.12   | LR77-v2.bin                                 |
|                  |                | CR10 v2         | 6.3.11   | CR10-v2.bin                                 |
|                  |                | UR5i v2L        | 6.3.12   | UR5i-v2L.bin                                |
|                  |                | RR75i v2        | 6.3.12   | RR75i-v2.bin                                |
|                  |                | LR77 v2L        | 6.3.12   | LR77-v2L.bin                                |
|                  |                | XR5i v2E        | 6.3.12   | XR5i-v2E.bin                                |
|                  |                | BIVIAS v2HC     | 6.3.11   | BIVIAS-v2HC.bin                             |
|                  |                | BIVIAS v2LC     | 6.3.11   | BIVIAS-v2LC.bin                             |
|                  |                | BIVIAS v2LL     | 6.3.11   | BIVIAS-v2LL.bin                             |
|                  |                | BIVIAS v2LH     | 6.3.11   | BIVIAS-v2LH.bin                             |
| BIVIAS v2HH      | 6.3.11         | BIVIAS-v2HH.bin |  |   |
| v2i              | ICR-2000       | ICR-2031        | 6.5.0  | ICR-203x.bin                                |
|                  |                | ICR-2041        | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)<br>N/A (T-Mobile US) | ICR-204x.bin                                |
|                  | ICR-2400       | ICR-2412        | 6.5.0  | ICR-241x.bin                                |
|                  |                | ICR-2431        | 6.5.0  | ICR-243x.bin                                |
|                  |                | ICR-2432        | 6.5.0  | ICR-243x.bin                                |
|                  |                | ICR-2436        | 6.5.0  | ICR-243x.bin                                |
|                  |                | ICR-2437        | 6.5.0  | ICR-243x.bin                                |
|                  |                | ICR-2438        | 6.5.0  | ICR-243x.bin                                |
|                  |                | ICR-2441        | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)<br>N/A (T-Mobile US) | ICR-244x.bin                                |
|                  | ICR-2500       | ICR-2501        | 6.5.0  | ICR-250x.bin                                |
|                  |                | ICR-2531        | 6.5.0  | ICR-253x.bin                                |
|                  | ICR-2600       | ICR-2631        | 6.5.0  | ICR-263x.bin                                |
|                  | ICR-2700       | ICR-2701        | 6.5.0  | ICR-270x.bin                                |
|                  |                | ICR-2734        | 6.5.0  | ICR-273x.bin                                |
|                  | ICR-2800       | ICR-2834        | 6.5.0  | ICR-283x.bin                                |



# Firmware Compatibility Chart

Notification Date: October 8, 2024

Page: 2 of 3



| Product Platform | Product Family | Product Name     | FW Version   | FW File Name           |
|------------------|----------------|------------------|--|------------------------|
| v3               | SmartStart     | SL302            | 6.5.0 <sup>1</sup><br>6.3.2 (PTCRB)<br>6.3.2 (AT&T)<br>6.3.1 (Verizon)                           | SPECTRE-v3L-LTE-US.bin |
|                  |                | SL304            | 6.5.0  | SPECTRE-v3L-LTE.bin    |
|                  |                | SL305            | 6.5.0  | SPECTRE-v3L-LTE.bin    |
|                  |                | SL306            | 6.5.0  | SPECTRE-v3L-LTE.bin    |
|                  | SmartFlex      | SR300            | 6.5.0  | SPECTRE-v3-ERT.bin     |
|                  |                | SR303            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  |                | SR304            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  |                | SR305            | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)                        | SPECTRE-v3-LTE-US.bin  |
|                  |                | SR306            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  |                | SR307            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  |                | SR308            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  |                | SR309            | 6.5.0  | SPECTRE-v3-LTE.bin     |
|                  | SmartMotion    | ST352            | 6.5.0  | SPECTRE-v3T-LTE.bin    |
|                  |                | ST355            | 6.5.0  | SPECTRE-v3T-LTE.bin    |
|                  | ICR-3200       | ICR-3201         | 6.5.0  | ICR-320x.bin           |
|                  |                | ICR-3211         | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)                        | ICR-321x.bin           |
|                  |                | ICR-3231         | 6.5.0  | ICR-323x.bin           |
|                  |                | ICR-3232         | 6.5.0  | ICR-323x.bin           |
|                  |                | ICR-3241         | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)                        | ICR-324x.bin           |
|                  |                | ICR-3241 Rev.2.0 | 6.5.0 <sup>1</sup><br>6.3.10 (PTCRB)<br>6.3.10 (AT&T)<br>6.3.10 (Verizon)<br>6.3.9 (T-Mobile US) | ICR-324x.bin           |
|                  |                | ICR-3241(W)-1ND  | 6.3.10   | ICR-324x-1n.bin        |
|                  | ICR-3800       | ICR-3831         | 6.5.0  | ICR-383x.bin           |



# Firmware Compatibility Chart

Notification Date: October 8, 2024

Page: 3 of 3



| Product Platform | Product Family | Product Name     | FW Version   | FW File Name    |
|------------------|----------------|------------------|--|-----------------|
| v4               | ICR-4400       | ICR-4401         | 6.5.0  | ICR-440x.bin    |
|                  |                | ICR-4434         | 6.5.0  | ICR-443x.bin    |
|                  |                | ICR-4453         | 6.5.0  | ICR-445x.bin    |
|                  |                | ICR-4461         | 6.5.0 <sup>1</sup><br>6.4.0 (PTCRB)<br>6.3.10 (AT&T)<br>N/A (Verizon)<br>N/A (T-Mobile US) | ICR-446x.bin    |
|                  |                | ICR-4461(xx)-1ND | 6.4.0<br>6.4.0 (PTCRB)<br>6.4.0 (AT&T)   | ICR-446x-1n.bin |
| v4i              | ICR-4100       | ICR-4133         | 6.5.0  | ICR-413x.bin    |
|                  |                | ICR-4161         | 6.5.0  | ICR-416x.bin    |
|                  | ICR-4200       | ICR-4233         | 6.5.0  | ICR-423x.bin    |
|                  |                | ICR-4261         | 6.5.0  | ICR-426x.bin    |
|                  |                |                  |  |                 |

<sup>1</sup> – Not certified for authorities stated in the rows below.

