

Notification Date: March 14, 2021
Effective Date¹: June 1, 2021

PRODUCT CHANGE NOTIFICATION

Fuse Change for ICR-3200

Product Identification

ICR-3200 product family with the product number (P/N) **ICR-3231(W)**, **ICR-3232(W)**, **ICR-3241(W)**, **ICR-3201(W)**, **ICR-3211B** and their variants.

Description of Change

Detailed Description of Change: From the effective date, the ICR-3200 routers with P/N listed above, will be equipped with new fuses in the main power circuits from BEL **0685T3000-01** to **0685T5000-01** or **0685T6000-01**. The 0685T5000-01 is fully functional and provides highly safe protection, the case with the 0685T6000-01 will occur only if the previous type will not be available in stores.

Anticipated impact on Fit, Form and Function: Change of the fuses improves the protection of the DC port against high overvoltage pulses.

Qualification Data

All these changes fulfill all internal quality requirements according to our Quality Management process and philosophy.

¹The effective date depends on storage supplies.