

**Notification Date:** September 1, 2024  
**Effective Date:** September 1, 2024

## PRODUCT CHANGE NOTIFICATION

# ICR-4[12]61(W) and ICR-4[12]33(W) Rev.1.1

## Product Identification


### Affected Products:

- This applies to the ICR-4[12]61(W) and ICR-4[12]33(W) products.
- See the product revision number on the packaging box or the product label to identify affected routers. Affected routers have the product revision *Rev.1.1*.
- The router GUI can also display the product revision under *Status* → *General* → *System Information* → *Product Revision*.
- Please note that the default revision (*Rev.1.0*) is neither printed on the label nor displayed in the GUI.

## Change Description

### Detailed Description of the Change:

- The housing now has 7 ANT holes instead of 6, with a distance of 16 mm between them instead of 17.5 mm.
- The front panel sticker reflects this change.
- In product versions with fewer than 7 ANT connectors, the extra holes are hidden by the front panel sticker.



## Anticipated Impact

### Detailed Description of the Impact:

- The reason for this change was the unification of housings in the ICR-4[12]61(W) and ICR-4[12]33(W) router models.
- All other product parameters remain the same.

## Qualification Data

The new version of the product fulfills all internal quality requirements according to our Quality Management process and philosophy.