

**ADVA**NTTECH

**WebAccess/VPN**

RELEASE NOTES

## Abstract

This document describes:

- Upgrade instructions for the software.
- Description of all new features, fixes and other implemented changes in the software.
- Description of known issues related to the software.

All related information, documents and binaries for the WebAccess/VPN application are available at <https://ep.advantech-bb.cz/products/software/webaccess-vpn> address.

## Software details

- **Version: 1.1.3**
- **Release date: October 27, 2021**

# **Part I**

## **Application Update Instructions**

## General Update Instruction and Notices

To check information about the application, including the version, go to *Application* menu located under the *Administration* section and check the *Application Information* box.

You can update the application on the same page as well. In the *Update WA/VPN Server* box click the *Choose File* button, choose a downloaded tarball file and click the *Update* button.

**Warning:** During the upgrade process from versions 1.1.0, 1.1.1, and 1.1.2 to the newer version. The automatic upgrade process of the User Modules, VPN Portal installed in the ICR routers (ICR-3xxx, ICR-2xxx, and ICR-4xxx) in the field doesn't work. This issue has been fixed in the 1.1.3 version. The work around this, is to install the User Modules VPN Portal 1.1.3 version manually in ICR routers. Other routers are not affected and automatic User Module upgrade works fine in all versions.

# **Part II**

## **Changelog**

**Enabled HTTP for proxy access**

Proxy links can now be accessed also without https prefix.

**Added support for V4 routers**

VPN portal client now works on V4 routers.

**Small fixes related to licenses**

Fixed incorrect router count check related to the maximum allowed by the license.