

Notification Date: September 01, 2020
Effective Date: September 01, 2020

PRODUCT CHANGE NOTIFICATION

Change Supply Voltage Range

Product Identification

List of all Affected Products:

- ICR-3831B, ICR-3831BD

Issue Description

Detailed Description of the Issue: Due to the HW changes on the PCB, the supply voltage range was changed. The original upper limit was 48 V, now the upper limit is 36 V. This information will be stated on the device labels and in the User manual.